



February 15 2016

Important Note: Sizing is based on the common industry description for a reducing tee. (Run-Run- Branch) OR (Main-Main- Outlet)

Socket Fusion Reducing Tees

| Size | Description | DR | Part # | Box QTY | Unit Weight | LIST | Special Notes/Approvals |
|-------------------|------------------|----|-------------------|---------|-------------|--------------------------|-------------------------|
| 3/4X3/4X1-1/4 | FAB REDUCING TEE | 11 | 3137R-75X125 | | | Non-stock call for P & D | |
| 1X3/4X3/4 | REDUCING TEE | 11 | 3137R-1X75X75 | 100 | 0.13 | \$7.88 | |
| 1X1X3/4 | REDUCING TEE | 11 | 3137R-1X75 | 100 | 0.18 | \$7.88 | |
| 1X1X1-1/4 | FAB REDUCING TEE | 11 | 3137R-1X1X125 | | | Non-stock call for P & D | |
| 1X1X1-1/2 | FAB REDUCING TEE | 11 | 3137R-1X1X150 | | | Non-stock call for P & D | |
| 1-1/4X3/4X3/4 | REDUCING TEE | 11 | 3137R-125X75X75 | 100 | 0.31 | \$10.71 | |
| 1-1/4X1X3/4 | REDUCING TEE | 11 | 3137R-125X1X75 | 100 | 0.34 | \$10.71 | |
| 1-1/4X1X1 | REDUCING TEE | 11 | 3137R-125X1X1 | 100 | 0.31 | \$10.71 | |
| 1-1/4X1X1-1/4 | REDUCING TEE | 11 | 3137R-125X1X125 | 100 | 0.31 | \$10.71 | |
| 1-1/4X1-1/4X3/4 | REDUCING TEE | 11 | 3137R-125X75 | 100 | 0.32 | \$10.71 | |
| 1-1/4X1-1/4X1 | REDUCING TEE | 11 | 3137R-125X1 | 100 | 0.31 | \$10.71 | |
| 1-1/2X3/4X3/4 | REDUCING TEE | 11 | 3137R-150X75X75 | 40 | 0.40 | \$18.90 | |
| 1-1/2X1X3/4 | REDUCING TEE | 11 | 3137R-150X1X75 | 40 | 0.39 | \$18.90 | |
| 1-1/2X1X1 | REDUCING TEE | 11 | 3137R-150X1X1 | 40 | 0.40 | \$18.90 | |
| 1-1/2X1-1/4X 3/4 | REDUCING TEE | 11 | 3137R-150X125X75 | 40 | 0.40 | \$18.90 | |
| 1-1/2X1-1/4X1 | REDUCING TEE | 11 | 3137R-150X125X1 | 40 | 0.40 | \$18.90 | |
| 1-1/2X1-1/4X1-1/4 | REDUCING TEE | 11 | 3137R-150X125X125 | 40 | 0.40 | \$18.90 | |
| 1-1/2X1-1/2X3/4 | REDUCING TEE | 11 | 3137R-150X75 | 40 | 0.40 | \$18.90 | |
| 1-1/2X1-1/2X1 | REDUCING TEE | 11 | 3137R-150X1 | 40 | 0.40 | \$18.90 | |
| 1-1/2X1-1/2X1-1/4 | REDUCING TEE | 11 | 3137R-150X125 | 40 | 0.40 | \$18.90 | |
| 2X3/4X3/4 | REDUCING TEE | 11 | 3137R-2X75X75 | 30 | 0.69 | \$19.95 | |
| 2X1X1 | REDUCING TEE | 11 | 3137R-2X1X1 | 30 | 0.69 | \$19.95 | |
| 2X1X1-1/4 | REDUCING TEE | 11 | 3137R-2X1X125 | 30 | 0.40 | \$19.95 | |
| 2X1X2 | REDUCING TEE | 11 | 3137R-2X1X2 | 30 | 0.45 | \$19.95 | |
| 2X1-1/4X3/4 | REDUCING TEE | 11 | 3137R-2X125X75 | 30 | 0.62 | \$19.95 | |



February 15 2016

Important Note: Sizing is based on the common industry description for a reducing tee. (Run-Run-Branch) OR (Main-Main- Outlet)

Socket Fusion Reducing Tees

| Size | Description | DR | Part # | Box QTY | Unit Weight | LIST | Special Notes/Approvals |
|---------------|------------------|----|-----------------|---------|-------------|--------------------------|-------------------------|
| 2X1-1/4X1 | REDUCING TEE | 11 | 3137R-2X125X1 | 30 | 0.70 | \$29.40 | |
| 2X1-1/4X1-1/4 | REDUCING TEE | 11 | 3137R-2X125X125 | 30 | 0.70 | \$27.30 | |
| 2X1-1/2X3/4 | REDUCING TEE | 11 | 3137R-2X150X75 | 30 | 0.70 | \$22.05 | |
| 2X1-1/2X1 | REDUCING TEE | 11 | 3137R-2X150X1 | 30 | 0.66 | \$22.05 | |
| 2X1-1/2X1-1/4 | REDUCING TEE | 11 | 3137R-2X150X125 | 30 | 0.66 | \$22.05 | |
| 2X1-1/2X1-1/2 | REDUCING TEE | 11 | 3137R-2X150X150 | 30 | 0.66 | \$22.05 | |
| 2X1-1/2X2 | FAB REDUCING TEE | 11 | 3137R-2X150X2 | | | Non-stock call for P & D | |
| 2X2X3/4 | REDUCING TEE | 11 | 3137R-2X75 | 30 | 0.66 | \$22.05 | |
| 2X2X1 | REDUCING TEE | 11 | 3137R-2X1 | 30 | 0.66 | \$22.05 | |
| 2X2X1-1/4 | REDUCING TEE | 11 | 3137R-2X125 | 30 | 0.66 | \$19.95 | |
| 2X2X1-1/2 | REDUCING TEE | 11 | 3137R-2X150 | 30 | 0.66 | \$22.05 | |
| 3X2X1-1/4 | FAB REDUCING TEE | 11 | 3137R-3X2X125 | | | Non-stock call for P & D | |
| 3X3X1 | FAB REDUCING TEE | 11 | 3137R-3X1 | | | Non-stock call for P & D | |
| 3X3X1-1/4 | FAB REDUCING TEE | 11 | 3137R-3X125 | | | Non-stock call for P & D | |
| 3X3X2 | FAB REDUCING TEE | 11 | 3137R-3X2 | | | Non-stock call for P & D | |
| 4X4X3 | FAB REDUCING TEE | 11 | 3137R-4X3 | | | Non-stock call for P & D | |